

TABLE 2
Sinkhole Inventory - Ft. Knox Base Housing
Anderson Golf Course, Ft. Knox Military Reservation, KY

Sinkhole Index Number	SINKHOLE SIZE AND SHAPE					WALL AND BOTTOM DESCRIPTORS				FILL DESCRIPTORS		Sinkhole Located in a Drainage Swale (Y/N)	Water Present (Y/N)	NOTES
	Width (ft)	Length (ft)	Depth (ft)	Elongated or Round?	Orientation	Rock walls?	Soil walls?	Rock bottom?	Soil bottom?	Fill Present in Sinkhole (Y/N)	Description			
S-100	100	100		Round	N/A	N	Y	N		N		Y	Y	Contain 4 "holes" within depression that appear to drain the area
S-101	5										evidence of dozer work and grading depression is earth-lined			Depression determined to be the result of grading work and not a sinkhole
S-102	35	35	±4	Round	N/A	N	Y	N	Y	Y	Rocks & Soils, Limbs, etc; has been filled;several small ±10' diameter depressions within overall depression	Y	N	Contains many small depressions
S-103	10	8		Round	N/A	N	Y			Y	Rocks and soil fill	Y	N	
S-104	50	50	1	Round	N/A	N	Y	N	Y	N		N	N	Contains 2-3' dropouts
S-105	50	50	4	Round	N/A	N	Y	N	Y	N		N	N	Contains 4' dropouts
S-106	7	50	4	Elongated	NW/SE	N	N	N	Y	N		Y	N	Contains several dropouts; Undetectable
S-107	100	150	2	Elongated	NE/SW	N	N	N	Y	N				
S-108														Sidewalk Placed over sinkhole, Beside entrance to clubhouse. Undetectable
S-109	50	50	<1-1/2	Round	N/A	N	Y	N	Y	Y	Soil Filled and Graded, probably for years. Dropout ±10' Dia, Depth 5'-6' per Kenny Shively	Y	N	